


# FM3-7340 INSTALLATION NOTE:

**PLEASE READ! THIS IS EXTREMELY IMPORTANT**

Failure to follow these instructions **WILL** cause a Main Driver PCB failure, which can cause E004 and/or E263 error codes!

**PLEASE USE CAUTION WHEN CONNECTING THESE UNIONS**



Join the 3 pin connector with 3 - Grey wires to the 3 pin connector with 3 - Yellow wires.

Join the 3 pin connector with 2 - White wires to the 3 pin connector with 2 - Purple wires.